## Bihar State Educational Infrastructure Development Corporation Limited, Patna

Physical status of construction of Examination Hall (BSEB)-2016 at Commissionary Headquarter

Report Dated: 31/08/2019

	Group No.	Division	Name of District	Name of Schools	PHYSICAL STATUS														Report Dated : 31/08/2019	
S.N.					Lay	Fou			ound oor			nd floo	r 3rd	l floor	4th floor		5th flo	Fil	ni C	Remarks
						ut tion		LL	RL	LL	RL	LL RI	. ш	RL	LL	RL	LL F	ء ا	et	
1	BSEB - 2	Bhagalpur	Bhagalpur	Jaglal H.S. School, Exam Hall, Bhagalpur													Х	ζ.		Roof Casted
2	BSEB - 3	Darbhanga	Darbhanga	Exam Hall, Darbhanga													X X			
3	BSEB - 4	Magadh	Gaya	Haridas Seminary High School, Exam Hall, Gaya													X X			
4	BSEB - 7	Munger	Munger	Zila School, Exam Hall, Munger													Х	2		
5	BSEB - 5	Tirhut East	Muzaffarpur	B. B. Collagiate, Muzaffarpur																Aluminium Work , Internal Painting External Putty, Steel work Running
6	BSEB - 1	Patna East	Patna	Exam Hall, Patna													X X			Puty ,paiting ,Aluminium Window,phed ,Electrical fitting in progress
7	BSEB-ADMIN	Patna East	Patna	ADMIN BLOCK IN BSEB CAMPUS, PATNA																Misc work (Flooring, plaster, putty ) is in progrees
8	BSEB - 8	Purnea	Purnea	Zila School, Exam Hall, Purnea													Х	ζ.		Handover
9	BSEB - 9	Koshi	Saharsa	Zila School, Exam Hall, Saharsa													х	ζ.		Almost complete
10	BSEB - 6	Saran	Saran	B. Seminary High School, Exam Hall, Saran													X	ζ.		All Roof Slabs Casted, External Plaster, Installation of Lift work is not started.
Tot	al No. of BSEB Ex	camination Ha	ll & Admin Block (BSEB)	10	0	0	0	0	0	0	0	0	0	0	0	1	0 0	6	3	