Bihar State Educational Infrastructure Development Corporation Limited, Patna

Physical status of construction of Examination Hall (BSEB)-2016 at Commissionary Headquarter

Report Dated: 31/10/2019

	Group No.	Division	Name of District	Name of Schools	PHYSICAL STATUS														Report Dated : 31/10/2019			
S.N.					Lay	Fou nda tion	da []	Grou		1st floo	or 2r	nd floor	3rd	floor	4th fl	oor 5	5th floor		Co mpl	Fin. Exp. (in lac)	Financial Achievement	Remarks
								ш	L RL	LL R	L L	L RL	ш	RL	ш	RL	L RL	-	ete		(%)	
1	BSEB - 2	Bhagalpur	Bhagalpur	Jaglal H.S. School, Exam Hall, Bhagalpur													X					Roof Casted
2	BSEB - 3	Darbhanga	Darbhanga	Exam Hall, Darbhanga												Х	Х					
3	BSEB - 4	Magadh	Gaya	Haridas Seminary High School, Exam Hall, Gaya												Х	X					
4	BSEB - 7	Munger	Munger	Zila School, Exam Hall, Munger													X					
5	BSEB - 5	Tirhut East	Muzaffarpur	B. B. Collagiate, Muzaffarpur																		Aluminium Work , Internal Painting External Putty, Steel work Running
6	BSEB - 1	Patna East	Patna	Exam Hall, Patna												X	X					Puty ,paiting ,Aluminium Window,phed ,Electrical fitting in progress
7	BSEB-ADMIN	Patna East	Patna	ADMIN BLOCK IN BSEB CAMPUS, PATNA																		Mislc work (Flooring, putty) is in progrees
8	BSEB - 8	Purnea	Purnea	Zila School, Exam Hall, Purnea													X					Handover
9	BSEB - 9	Koshi	Saharsa	Zila School, Exam Hall, Saharsa													X					
10	BSEB - 6	Saran	Saran	B. Seminary High School, Exam Hall, Saran													X X					All Roof Slabs Casted, External Plaster, Installation of Lift work is not started.
Total No. of BSEB Examination Hall & Admin Block (BSEB)				10	0	0	0	0	0	0 0	0	0	0	0	0	1 0	0	5	4	0	0	